




## Cone Point Grub Screws ISO 4027 (DIN 914)

Also known as a set screw, these headless types of screws have many uses. This particular type has a hex socket drive, and a cone point on the opposite end, as to ISO 4027 or DIN 914.



d	t	s	e
<b>M2</b>	0.8/1.7	0.9	1.003
<b>M2.5</b>	1.2/2.0	1.3	1.427
<b>M3</b>	1.2/2.0	1.5	1.730
<b>M4</b>	1.5/2.5	2	2.300
<b>M5</b>	2.0/3.0	2.5	2.870
<b>M6</b>	2.0/3.5	3	3.440
<b>M8</b>	3.0/5.0	4	4.580
<b>M10</b>	4.0/6.0	5	5.720
<b>M12</b>	4.8/8.0	6	6.860
<b>M16</b>	6.4/10.0	8	9.150
<b>M20</b>	8.0/12.0	10	11.430