




Flat Point Grub Screws ISO 4026 (DIN 913)

Also known as a set screw, these headless types of screws have many uses. This particular type has a hex socket drive, and a flat on the opposite end, as to ISO 4026 or DIN 913.



d	thread pitch	dp	t min.	t max.	s	e
M2	0.40	0.75	0.8	1.7	0.9	1.003
M2.5	0.45	1.25	1.2	2.0	1.3	1.427
M3	0.50	1.75	1.2	2.0	1.5	1.730
M4	0.70	2.25	1.5	2.5	2.0	2.300
M5	0.80	3.20	2.0	3.0	2.5	2.870
M6	1.00	3.70	2.0	3.5	3.0	3.440
M8	1.25	5.20	3.0	5.0	4.0	4.580
M10	1.50	6.64	4.0	6.0	5.0	5.720
M12	1.75	8.14	4.8	8.0	6.0	6.860
M16	2.00	11.57	6.4	10.0	8.0	9.150
M20	2.50	14.57	8.0	12.0	10.0	11.430